

ਵੱਲ

Principal,
Akai Academy,
Benra, Distt. Sangrur.

ਨੰਬਰ 163

ਮਿਤੀ: 10-07-2025

ਵਿਸ਼ਾ: ਸਕੂਲ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।
(Akai Academy, Benra, District Sangrur)

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫ਼ਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2025-26 (31.03.2026) ਤੱਕ ਬਾਹਰੇ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿਚ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫ਼ਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਈ-ਚਲਾਨ/ਰਸੀਪਟ ਨੰ. 18275887 ਮਿਤੀ 08-07-2025 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ/ਸੇਫਟੀ ਰਿਪੋਰਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2, ਲੋ.ਨਿ.ਵਿ.
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ।

ਮਿਤੀ

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 2500 ਮਿਤੀ 09.06.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

— ਸ਼ਾਹੀ —

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2, ਲੋ.ਨਿ.ਵਿ.
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ।


Building Safety Report

Name of School: - Akal Academy, Benra, District Sangrur

As per report of Er. Varinder Kumar, Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:

1. The Parameters to check the stability and safety of building such as Structural Design, Architectural Drawings, bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this, inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 32507 Sqft which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2025-26 is 10,000/-

As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use for One year up to 31-03-2026 subject to the above conditions.



Sub-Divisional Engineer,
Const. Sub Division No.2,
PWD B&R, Malerkotla.